



USB VCOM Driver Read Me

Version 2.2.0

Table of Contents

1. NEW FEATURES FOR THIS RELEASE.....	1
2. ENHANCEMENTS/IMPROVEMENTS/FIXES.....	1
3. OUTSTANDING ISSUES	1
4. SOFTWARE/READER TOOL COMPATIBILITY	2
5. TECHNICAL SUPPORT INFORMATION	2

1. NEW FEATURES FOR THIS RELEASE

- Added support for CR82xx readers
- Upgraded installer with SHA-2 Certificate

2. ENHANCEMENTS/IMPROVEMENTS/FIXES

VCOM Driver 2.2.0

- Feature enhancements only

VCOM Driver 2.1.0

- Add support for multiple cabled VCOM devices and a single modem VCOM device.
- Added the capability for a silent install.

3. OUTSTANDING ISSUES



4. SOFTWARE/READER TOOL COMPATIBILITY

Recently upgraded Code software is available for download from Code website at: www.codecorp.com or contact Code Technical Support.

- CortexTools™- 2.5.26
- Modem Firmware 2010, 2210, 2410
- CR80xx Reader firmware version 1220
- CR50xx Reader firmware version 1234
- CR82xx Reader firmware version 1.1.0

5. TECHNICAL SUPPORT INFORMATION

You may contact Code at:

Code Corporation
12393 South Gateway Park Place
Suite 600
Draper, UT 84020

Voice: 801-495-2200

Fax: 801-495-0280

support@codecorp.com

You can track new product releases, software updates and technical bulletins by visiting the Code web page at <http://codecorp.com>.

If you have technical questions visit our website at <http://codecorp.com/contact.php> for phone numbers and email addresses.

Disclaimer:

Copyright© 2014-2017 Code

All Rights Reserved

The software described in this ReadMe file may only be used in accordance with the terms of its License Agreement. No part of this publication may be reproduced in any form or by any means without written permission from Code Corporation. This includes electronic or mechanical means such as photocopying or recording in information storage and retrieval systems.

NO WARRANTY. This technical documentation is provided AS-IS. Further, the documentation does not represent a commitment on the part of Code Corporation. Code Corporation does not warrant that it is accurate, complete or error free. Any use of the technical documentation is at the risk of the user. Code Corporation reserves the right to make changes in specifications and other information contained in this document without prior notice, and the reader should in all cases consult Code Corporation to determine whether any such changes have been made. Code Corporation shall not be liable for technical or editorial errors or omissions contained herein; nor for incidental or consequential damages resulting from the furnishing, performance, or use of this material. Code Corporation does not assume any product liability arising out of or in connection with the application or use of any product or application described herein.

NO LICENSE. No license is granted, either by implication, estoppels, or otherwise under any intellectual property rights of Code Corporation. Any use of hardware, software and/or technology of Code Corporation is governed by its own agreement.

The following are trademarks or registered trademarks of Code Corporation:

CodeXML®, Maker, QuickMaker, CodeXML® Maker, CodeXML® MakerPro, CodeXML® Router, CodeXML® Client SDK, CodeXML® Filter, HyperPage, CodeTrack, GoCard, GoWeb, ShortCode, GoCode®, Code Router, QuickConnect Codes, Rule



Runner®, Cortex®, CortexRM, CortexMobile, Code, Code Reader, CortexAG, CortexStudio, CortexTools, Affinity®, CortexDecoder, CortexJPOS, CortexOPOS.

All other product names mentioned in this Read Me file may be trademarks of their respective companies and are hereby acknowledged. The software and/or products of Code Corporation include inventions that are patented or that are the subject of patents pending.

Apple and iPhone are trademarks of Apple Inc., registered in the U.S. and other countries.

Windows is a trademark of Microsoft Corporation in the United States and/or other countries.

